


Reliability concerns with the SNS Machine protection Sytem

Doug Curry,
Eric Breeding,
Alan Justice

ARW May 1, 2015




Overview

- Leading causes of reliability issues at SNS
 - False trip reports
 - Excessive trip delays
 - Fail to deliver fault status
- Additional reliability concerns at SNS
- 2nd Generation Highlights



False trip reporting

- Excessive Common Mode currents on input channels




- Mitigation techniques
 - Redesigned interface module with integrated ferrites that cover broad frequency range
 - Replaced Power Supply opto-couples with lower dynamic range but higher CMRR

Excessive system delays



Failure to deliver fault status

- Output enable stuck high




- Provides a false MPS status to the top level node and permits continued beam production


- Firmware implementation did not match the architecture approved by the review committee

- Single clock source generated at the lowest node in the chain
 - Each node simply grants or prevents the passing of the permissive signal
- Passed local clock reference instead of original clock source

Reporting false positive MPS status




What got installed



What was approved

Additional reliability issues at SNS

- Low current drivers
 - Increased complexity
 - Non-standard configuration
- High density connectors
 - Bent pins “stuck high” status shorted to power pin
- PLC interfaces
 - Single digital output interface “solid state output”
- Operating System errors
 - Software interlocks
- Hardware Assembly inconsistencies



Methods for improving system reliability

- Power measurement checks performed every 6 months
 - Plot the output power of fiber transmitters over time to identify degrading components
- 100% system verification checks performed after every extended outage
- Standardized testing procedures for improved consistency
- Equipment status tags
 - Red, yellow, and green tags

Modernization is imperative to achieve high reliability and maintainability

- Aging hardware increases the probability of failures within the MPS.
- Failures must be mitigated quickly to achieve the high availability goals of the SNS.
- Unfortunately, the MPS is comprised of several obsolete components. Component obsolescence prevents the acquisition and maintenance of a safe supply of spare parts.
- As failures become more likely, the existing inventory of spare parts will become depleted.

Modernization affords a unique opportunity to improve MPS reliability and functionality

- Failure points are reduced through simplification of the Fast Protect System (FPS) architecture.
- Functionality required for second target station (STS) may be fully implemented with the new FPS hardware .
- Lessons learned over years of operating the accelerator may be applied with new FPS hardware.
- Development of better in-system diagnostics will be feasible with modern components and devices.

Proposed Architecture Achieves a Significant Reduction in Hardware

	Current System	Proposed System
MPS Chassis	102	60
Interface Chassis	20	0
Programmable Interface Chassis	5	0
VME Chassis	8	0
VME Computer	8	0
Rear Transition Board	102	0
VME PMC Expansion Boards	24	0
Field Node Cards **FPGA	102	60
MPS Master Chassis	1	1
MPS Trigger Control Chassis	1	0
MicroTCA Cards	0	4
Linux Workstation/uTCA IOC	0	1
VME Computer	1	0
Total Hardware Count	382	126

Legacy data courtesy of Alan Justice

67% Reduction in Failure Points

Consolidation of Hardware Into Fewer Entities Mitigates Cable-Induced Failures



	Current System	Proposed System
SCSI Cables	206	0
Fiber Links	204	65
Timing Links	226	2
Miscellaneous MPS Links	14	7
<i>Total # of Interconnects</i>	<i>650</i>	<i>74</i>

Data courtesy of Alan Justice


89% Reduction in Failure Points

The Field Node Has Significantly Fewer Components and Interconnects

Hardware assembly



Proposed MPS Setup



- No software interfacing to EPICS at field nodes
- No RTDL/Event Link
- No VME SBC

Figures courtesy of Alan Justice


Current configuration

High density connections


Required hardware for Deployment

- VME Crate
- VME IOC
- MPS chassis
- Teknobox PMC card
- **VME PMC Span
- SCSI Cables
- RTDL and Event Link cables
- Rear Transition Card


Front




Rear



Leverage Readily Available COTS Hardware To Expedite Deployment



Software interlocks
"chatter faults"



SNS 2nd Generation System

- System integrity checks prior to the production of each beam pulse
 - Verify one channel per machine cycle
 - Full MPS system verification checks completed every 30 seconds for 1800 input channels
 - 100% status reports from all interface modules required prior to cycle production
 - SFP “fiber” status
- Standardized modules
 - Hot swappable for increased interface flexibility and maintainability “leave chassis in place”
- Increase Timing System coupling Interface to provide improved post mortem analysis event

The new architecture Shall Reside Within Legacy Infrastructure


- The proposed FPS will be “form, fit and function compatible” with the legacy system to the greatest extent possible.
- The new FPS hardware shall reside in equipment racks that house the legacy FPS.
- Each FPS node shall accept existing input field wiring.
- All modules shall be compatible down to the pin level with the legacy FPS chassis and all field inputs.

Questions???

Beautiful Dance Moves



$\sin(x)$



$\cos(x)$



$\tan(x)$



$\cot(x)$



$|x|$



x



x^2



$x^2 + y^2$



\sqrt{x}



$\sqrt{-x}$



$\frac{1}{x}$



crap.